

What is Electro Scan & How Can it Help SAM?



Sewer Authority Mid-Coastside Board Meeting

July 22th, 2019



Carissa Boudwin
Vice President, Electro Scan Inc.
carissa@electroscan.com

SAM Board Meeting / Electro Scan Inc.


electro
scan**inc.**

electro**scan****inc.**

What Are We Missing?




2010 EPA Study




Electro Scan Inc. | Copyright © 2019. All Rights Reserved.

Page 3

2010 EPA Study




CCTV OPRI



FELL ■ Large ■ Medium ■ Small

2010 EPA Study



CCTV ■ OPRI


FELL ■ Large ■ Medium ■ Small

"CCTV was not a good indicator of sources of infiltration. In fact, it recorded even fewer infiltration related defects after cleaning."

April 27, 2017 California EPA Office of Enforcement



Best Practice



ASTM F2550-13 (2018)



Designation: F2550 - 13

Standard Practice for Locating Leaks in Sewer Pipes By Measuring the Variation of Electric Current Flow Through the Pipe Wall¹

This standard is issued under the fixed designation F2550; the number immediately following the designation indicates the year of original adoption or revision. The word "revised" indicates that a later revision has been made.

INTRODUCTION

Interruptions of groundwater flow through defects in the pipe can considerably increase the oxygenation and reduce levels of dissolved oxygen in a sewer. A pipe may cause degradation of aquifers and shoreline waters. Accurate location, measurement, and characterization of all potential pipe leak defects are essential inputs for cost-effective design, testing, and certification of pipe repairs, renewal, and new construction. While commonly used sewer leak assessment methods, such as air and water pressure testing, represent cost effective methods to provide overall visual inspection of pipes, they are unable to provide accurate location and size of leaks, particularly at individual joints and service connections, limit their use in remediation and rehabilitation decision support.

1. Scope

1.1 This practice covers procedures for measuring the variation of electric current flow through the pipe wall to locate defects that are potential water leakage paths either in or out of the pipe.

1.2 This practice applies to manhole and lateral gravity flow storm sewers, sanitary sewers, and combined sewers with diameters between 3 and 60 in (75 and 1500 mm). The pipes must be free of obstructions that prevent the probe passing through the pipe.

1.3 The scanning process requires access to sewers, lifting sewers, and operations along roadways, but no safety hazard. This standard does not describe the specific safety hazards encountered or the specific procedures that must be carried out when operating in these hazardous environments. (7.1.3) There are no safety hazards specifically associated with the use of an electrical apparatus as defined in the specifications provided in this standard. (6.7 and 6.10.1)

1.4 The measurement of the variation of electric current requires the insertion of various items into a sewer. There is

a sharp, sharp tip to induce minor structural condition in the sewer and it may become lodged in the pipe or may cause the state of a sewer in poor structural condition to further deteriorate. This standard does not describe methods to assess the structural risk of a sewer.

1.5 The values stated in inch-pound units are to be regarded as standard. The values given in parentheses are mathematical conversions to SI units that are provided for information only and are not considered standard.

1.6 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and to determine the applicability of regulatory limitations prior to use.

2. Terminology

2.1 *Definition of Terms Specific to This Standard:*

2.1.1 *lateral*, n—sewer pipe connecting the common sewer collection system to the user.

2.1.2 *manhole*, n—pipe that is part of the common sewer collection system.

2.1.3 *maintenance hole*, n—MHz vertical shafts intersecting a sewer that allows entry to the sewer for cleaning, inspection, and maintenance.

2.1.4 *owner*, n—entity holding legal rights to, and responsible for the operation and maintenance of the sewer pipe.

2.1.5 *probe*, n—scan electrode placed in a pipe.

¹This practice was developed by the Committee on Sewerage, Drainage and Water Quality and is the result of joint efforts of Subcommittee F25.2 on Inspection and Repair of Sewer and Wastewater Facilities.

Copyright © ASTM International. 100 Bar Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959. United States

1Copyright © 2018 Electro Scan Inc. All Rights Reserved.



ASTM INTERNATIONAL

Helping our world work better

All

Search topic, title, author, A53

Long

PRODUCTS & SERVICES | GET INVOLVED | ABOUT | NEWS

Products and Services | Standards & Publications | Standards Products

Standards & Publications

All Standards and Publications

Standards Products

Symposia Papers & STPs

Manuals, Monographs, & Data Series

Journals

Reading Room

Authors

Book of Standards

Reading Room

Product Updates

Catalogs

Digital Library

ASTM F2550 - 13(2018) ◉

Standard Practice for Locating Leaks in Sewer Pipes By Measuring the Variation of Electric Current Flow Through the Pipe Wall

Active Standard ASTM F2550 | Developed by Subcommittee: F36.20



Book of Standards Volume: 04.12

Format	Pages	Price	Add To Cart
PDF	7	\$46.00	ADD TO CART
Hardcopy (shipping and handling)	7	\$46.00	ADD TO CART


electro^oscan^{inc.}

Electricity Mimics Water with Path of Least Resistance





Positional Accuracy Testing



Electro Scan Demo Report

SEWER AUTHORITY MID-COAST STAR WASTE WATER TREATMENT FACILITY

Half Moon Bay, CA
Field Work: July 15th, 2019

electro scan inc.

SAM Board Meeting Electro Scan Inc.

Page 12

Electro Scan Field Results

Electro Scan Inc. conducted its field demonstration on Monday, July 15th, 2019 including two (2) sewer mains.

As shown in Table 1, Electro Scan surveyed 834 linear feet of pipe finding 342 pinholes and 27 individual defect locations contributing an estimated 287.01 gallons per minute (GPM) of defect flow or 413,294 gallons per day (GPD).

Table 1: Half Moon Bay Electro Scan Demonstration Summary Results

	Scans	Footage	Pinholes	Total Defects	GPM	GPD
Total:	2	834	342	27	287.01	413,294

Listed In Inspection Order

Date	Mainline ID	Pipe ID	Pipe Type	Diameter	Distance (ft)	Pinhole	Small	Medium	Large	GPM	GPD	GPD IDM
7/15/2019	MH 21 - MH 22	MH 21 - MH 22	CIPP	21	430.84	342	2	0	0	270.37	389,333	227,204
	MH 20 - MH 21	MH 20 - MH 21	VCP	21	402.84	0	25	0	0	16.64	23,962	14,955


Note: Due to low water height in pipe, defects could be more numerous & more severe than stated in report.

Summary

While CCTV inspection provides a visual recording of internal pipe conditions, Electro Scan's findings confirm that Electro Scan represents a more dependable method to find and measure defects in the wall of sewers and at joint fittings. Please refer to the Appendix for additional information.

All work was completed in accordance with the Seventh Edition, Volume 1, of the Operations and Maintenance of Wastewater Collection Systems manual, with all locations accurate to within 1 cm (0.4m in) and ±30% accuracy of its defect flow calculations which assume a 1ft head and 1% pipe gradient. All reporting was prepared in accordance with ASTM F2550.

Demo Location



Demo Location: Bev Cunha's Country Rd



Field Photos: July 15th, 2019


Thanks For A Great Day! The Electro Scan Team



MH 21 – MH 22


Cured-In-Place Pipe (CIPP)

MH 21 – MH 22



1

MH 21 – MH 22 – Defect Current



1

MH 21 – MH 22 – Defect Chart

Page 1 of 12

2 Small Defects = 4% of Estimated Defect Flow

	Defects	Length of Defects (f..)	GPM	% of GPM	GPD	GPDI/DM
Total:	2	1.909	11.130	4%	16,027	9,353

DEFECT BY LOCATION Mainline ID: MH 21 - MH 22 Pipe ID: MH 21 - MH 22 Diameter: 21 inches Pipe Type: CIPP Soil Type: Sandy Clay Loam Ground Condition: Dry Pinholes Not Included							
Defect Grade	Defect Start (ft)	Defect End (ft)	Length of Defects (ft)	GPM	% of GPM	GPD	GPDI/DM
S	27.50	28.71	1.21	6.11	2.26%	8,798	5,135
S	84.34	85.03	0.70	5.02	1.86%	7,229	4,219

Pinholes = 96% of Estimated Defect Flow

	Defects	Length of Defects (f..)	GPM	% of GPM	GPD	GPDI/DM
Total:	342	35.941	259.210	96%	373,262	217,826




DEFECT BY LOCATION Mainline ID: MH 21 - MH 22 Pipe ID: MH 21 - MH 22 Diameter: 21 inches Pipe Type: CIPP Soil Type: Sandy Clay Loam Ground Condition: Dry Pinholes Only							
Defect Grade	Defect Start (ft)	Defect End (ft)	Length of Defects (ft)	GPM	% of GPM	GPD	GPDI/DM
X	7.20	7.20	0.00	0.12	0.04%	173	101
X	13.37	13.44	0.08	0.62	0.23%	893	521
X	18.17	18.17	0.00	0.11	0.04%	158	92
X	18.47	18.54	0.08	0.42	0.16%	605	353
X	18.74	18.74	0.00	0.10	0.04%	144	84
X	20.30	20.77	0.47	2.66	0.98%	3,830	2,235
X	20.65	20.65	0.00	0.13	0.05%	187	109
X	31.78	31.83	0.05	0.38	0.14%	547	319
X	32.08	32.55	0.47	2.62	0.97%	3,773	2,202
X	33.02	33.12	0.10	0.65	0.24%	936	546
X	34.43	34.51	0.08	0.63	0.23%	907	529
X	35.08	35.67	0.59	4.00	1.48%	5,760	3,361

"My former students are experiencing CIPP & VCP leaks that were OK'd by CCTV. Do you know any device that can find leaks in CIPP liners?"

2010

Ken Kerri, Ph.D., P.E.

One Year Later




Post-CIPP Warranty Inspection


CIPP Leakage After Multiple
Wet Weather Events

12/19/2018
Post-CIPP Warranty Inspection

643 Days
1 year, 9 months, 3 days
21 months, 3 days




36.4 GPM




Post-CIPP

3/17/2017
Post-CIPP Inspection



20.9 GPM



CIPP Should Be Watertight. After All It's a Pipe!

GOOD CIPP

No Electrical Current Should Ever
Pass Through a New Liner.

BAD CIPP


If Electric Current
Passes Through a Liner,
A CIPP Leak is Found.




Perfect CIPP Liner

DEFECTS		% OF DEFECT LENGTHS	GPM SUMMARY	DIAMETER & DISTANCE	OPERATOR INFO
Small	0	0	Minor 0.000 Moderate 0.000 Severe 0.000 Total GPM 0.000 GPD 0 GPD IDM 0 Minor % 0.00% Moderate % 0.00% Severe % 0.00%	8 293.00 ft	Tech Electroscan Project Demo Job Demo Atmospheric Test 2/21/2018 3:01:02 PM Scan Start 2/21/2018 4:04:59 PM
Medium	0	0			
Large	0	0			
All Defects	0	0			


DEFECT CURRENT Mainline ID: 118-203434 - 188-203433 Pipe ID: 118-203434 - 188-203433 Diameter: 8 inches Pipe Type: CIPP Soil Type: Ground Condition:



WATER HEIGHT AND PROBE SPEED Mainline ID: 118-203434 - 188-203433 Pipe ID: 118-203434 - 188-203433 Diameter: 8 inches Pipe Type: CIPP Soil Type: Ground Condition:



Monterey, California
July 2015




wrc Masterclass on Electro Scanning Inspection



2016

This presentation highlights new technology and its recent results from British water clients, showing how it provides specific locations for each defect and an estimated defect flow in litres per second can help prioritize rehabilitation and certify newly rehabilitation pipes as 'leak free.'

Peter Henley, WRc



WRc Delivers the
Next Generation in
Sewer Leak
Detection



by Peter Henley of WRc and Mark
Grabowski of Electro Scan Inc.

Electro Scan Inc. | Copyright © 2016. All Rights Reserved.


Page 27

2

MH 20 – MH 21 Vitrified Clay Pipe (VCP)


2

MH 20 – MH 21



2

MH 20 – MH 21 – Defect Current



MH 20 – MH 21 – Defect Chart

	Defects	Length (ft)	GPM	% of GPM	GPD	GPD/IDM		
Total:	25	1.188	17.080	103%	24,595	15,351		
DEFECT BY LOCATION		Mainline ID: MH20 - MH21	Pipe ID: MH20 - MH21	Diameter: 21 inches	Pipe Type: VCP	Soil Type: Sandy Clay Loam	Ground Condition: None	Ranked By GPM
Defect Grade	Defect Start (ft)	Defect End (ft)	Length (ft)	GPM	% of GPM	GPD	GPD/IDM	
S	379.92	380.02	0.10	1.33	7.99%	1,915	1,195	
S	330.29	330.39	0.10	1.24	7.45%	1,786	1,114	
S	152.90	153.00	0.10	1.10	6.61%	1,584	989	
S	386.97	387.05	0.08	1.04	6.25%	1,498	935	
S	287.74	287.81	0.07	0.96	5.77%	1,382	863	
S	89.09	89.16	0.08	0.91	5.47%	1,310	818	
S	394.10	394.17	0.07	0.90	5.41%	1,296	809	
S	10.99	11.04	0.05	0.73	4.39%	1,051	656	
S	301.97	301.99	0.02	0.46	2.64%	634	413	
S	301.97	301.99	0.03	0.46	2.76%	662	413	
S	110.35	110.38	0.02	0.46	2.76%	662	413	
S	337.37	337.39	0.03	0.45	2.70%	648	404	
S	280.61	280.63	0.03	0.45	2.70%	648	404	
S	273.60	273.63	0.03	0.44	2.64%	634	395	
S	252.36	252.39	0.02	0.42	2.52%	605	377	
S	124.49	124.49	0.00	0.22	1.32%	317	198	
S	82.01	82.01	0.00	0.22	1.32%	317	198	


“CAMERAS MISS 80-100% OF LEAKS.”




Ken Kerri, Ph.D., P.E.
2010

CCTV Can't
Look Inside Joint
or Turn 90-Degrees


CCTV Can't See Inside
But FELL Can!




Why Do Cities Electro Scan VCP & Other Pipes?



Scan 1





**electro
scan^{inc.}**

Electro Scan Inc.
1745 Markston Road
Sacramento, CA 95825-4026
Tel: 916-779-0660
<http://www.electroscan.com>

Electro Scan Inc. | Copyright © 2019. All Rights Reserved.



10,000 Sq Ft