

Mirada Road Bridge

The Mirada Road Bridge (formerly known as Miramar Bridge) shown here in 1918.



Mirada Road Bridge (formerly known as Miramar Bridge) in 1979





Concrete arch bridge west side looking towards the east – January 2021 – Ped Bridge closed 7/2019



Arch bridge looking at the west side of bridge – January 2021



Arch bridge east side looking towards the west – January 2021



Abandoned sanitary sewer pipe on the east side of bridge



Mirada Road Bridge after 12/15/2021 when concrete arch collapsed, east side of bridge, abandoned sewer pipe pictured in the creek bed.



Mirada Road Bridge after 12/15/2021, west side of bridge.



Mirada Road Bridge looking north – barricades and caution tape added by the Road Division on 12/22/2021